

TRAIL ASSESSMENT FORM

Doc. #	2022	Trail Name	Trail (no name)	Trail Type:	MTB	Condition	Good
Route:		From Bugbee just east of mk2096, north, to just east of mk2094					
Recent Weather:		Clear and dry					
TRAIL LANDMARKS		Very short connector path starts at Bugbee/White Loop East just east of mk2096. 66yd to end at White Loop West					
MINOR PROBLEM AREAS		Some bn					
MAJOR PROBLEM AREAS							
DISTANCES TO MAJOR INTERSECTIONS		66yd from Bugbee just east of mk2096, north, to just east of mk2094					
Report prepared by:			Steve Cobble		Assessment date:		05/12/08

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

- | | | |
|-------------------------|-------------------------------------|------------------------|
| waterbars (wb) | small blowdowns (sbd) | |
| culverts(cv) | large blowdowns (lbd) | |
| rolling dips (rd) | rock work (rkw) | |
| bridges (br) | bridge building (bbd), ditches (dt) | corrugated plastic(cp) |
| excessive erosion (ee) | leaning tree (lt)) | |
| intersection marker(mk) | dugout(du) | |
| bog bridges (bb) | culvert replacement (cr) | |
| non-functioning(nf) | functioning(fc) | |
| damage(dg) | | |
| not needed(nn) | | |
| cm (corrugated metal) | | |
| rock stairs (rs) | trail relocation (tr), | |
| cribbing (cb) | building new trail drainage (ntd) | |
| retaining walls (rw) | brushing needed (bn) | |
| clay(cl) | | |
- MTB(mountainbikes allowed)
(mk2042) meaning not on DCR map