

## TRAIL ASSESSMENT FORM

<b>Doc. #</b>		<b>Trail Name</b>	Furnace Brook Trail	<b>Trail Type:</b>	<b>Wide - M</b>	<b>Condition</b>	Good
<b>Route:</b>		Indian Camp Path 4120 – Craggs Foot Path 4142					
<b>Recent Weather:</b>		Sunny in the 80's. No rain for last couple weeks.					
<b>TRAIL LANDMARKS</b>		<ul style="list-style-type: none"> <li>• Trailhead leaves Indian Camp Path at Marker 4120. Treadway is road width.</li> <li>• Culvert in streambed under treadway at 375 feet. R to L w/ rkw/earthen wells on both sides. Two 15" corrugated PVC pipes.</li> <li>• Treadway turns into a footpath from 470 feet through .18 miles.</li> <li>• Treadway returns to road width at .30 miles.</li> <li>• Furnace Brook Trail ends at its intersection with Craggs Foot Path at Marker 4142 at .33 miles. Rockwork around intersection marker tree noted.</li> </ul>					
<b>MINOR&amp;MAJOR PROBLEM AREAS</b>		None					
<b>DISTANCES TO MAJOR INTERSECTIONS</b>		<ul style="list-style-type: none"> <li>• Indian Camp Path Marker 4120 to Craggs Foot Path Marker 4142 - .33 miles</li> </ul>					
<b>Report prepared by:</b>			Bob Flagg		<b>Assessment date:</b>		8/4/16