

## TRAIL ASSESSMENT FORM

<b>Doc. #</b>		<b>Trail Name</b>	Pleasant Trail	<b>Trail Type:</b>	Wide	<b>Condition</b>	Good
<b>Route:</b>		Headquarters Path 4046 – Indian Camp Path 4086 & 4085					
<b>Recent Weather:</b>		Partly sunny, mid 40's, Rain within last 24 hours.					
<b>TRAIL LANDMARKS</b>		<ul style="list-style-type: none"> <li>• Trailhead starts at Headquarters Path Marker 4046.</li> <li>• Rock wall crosses to the left and right of the treadway at 200 feet.</li> <li>• Culvert under treadway in streambed at .23 miles. Rockwork/earthen construction with clay 36" pipe. Flowing fine.</li> <li>• Spur path to Indian Camp Path Marker 4086 leaves on left at .33 miles.</li> <li>• Pleasant Trail ends with its intersection with Indian Camp Path at Marker 4085 at .36 miles. Signage on tree locates the Green Dot loop NE.</li> </ul>					
<b>MINOR&amp;MAJOR PROBLEM AREAS</b>		None					
<b>DISTANCES TO MAJOR INTERSECTIONS</b>		<ul style="list-style-type: none"> <li>• Headquarters Path Marker 4046 to Indian Camp Path Marker 4085 - .36 miles.</li> </ul>					
<b>Report prepared by:</b>			Bob Flagg		<b>Assessment date:</b>		3/18/16