## Friends of the Blue Hills

## **Trail Volunteer Work Report**

Work date (mm/dd/yy): 7/12/15 Report date: 7/13/15

Your name: Mimi Kugler

List Volunteers working with you:

**Trail Name/description (one trail** Breakneck Ledge Path name only):

Section Name (select one from the drop down list): Blue Hills

## Work Completed (Please be specific with location of work. Note hazards & potential hazards addressed if applicable):

Raked out the following drainage structures, including the outflow ditches, to remove leaves and pine needles, shoveled out stones from these structures, and reshaped the structures and ditches (distances from Wolcott Path):

Grade reversal at 200 ft (formerly a wood waterbar) Grade reversal at 266 ft (formerly a rolling dip) Ledge waterbar at 367 ft Rolling dip at .17 miles

Checked cuverts at .48 and .49 miles. Both were clear of branches and other obstructions. Raked leaves out of entry and exit areas of culverts.

Limited brushing.

Made two small notches in the tiny berms near the largest mud pit, in hopes of allowing water drainage from the mud pit. This area is quite flat, but water drains into the trail from Hancock Hill.

Total Hours (# of people x hours worked. Use # of people x 3.5 for trail maintenance events): 2.50

## Work Remaining:

It would be helpful to bring in some gravel to build up the crown of the trail at the mud pit(s), and also use the gravel to cover the exposed part of the corrugated plastic pipe that makes up the top of the south culvert (north of intersections 1178/1180).

Other comments (areas of concern, wildlife sightings, trail markings and signage condition, need for re-route, possible encroachment):

Forward completed electronic form to: Dexter Robinson @ dexpcdoc@gmail.com