Friends of the Blue Hills

Trail Volunteer Work Report

Work date (mm/dd/yy): 12/24/12 Report date: 12/26/12

Your name: Bob Flagg

List Volunteers working with you:

Trail Name (one trail name only): Sawcut Notch Path

Section Name/Description:

Near Marker 4066

Work Completed (Please be specific with location of work. Note hazards & potential hazards addressed if applicable):

Installed two stone hardened grade reversals at the site of a failed grade reversal just west of Marker 4066. Brushed trail of branches and some green briar from Rt 28 to marker 4066.

Total Hours (# of people x hours worked): 5.50

Work Remaining:

There is a culvert west of this work that needs attention. The stone surrounding the outflow of the culvert is leaning away from the trail and is in danger of collapsing. Need to remove the stone and rebuild.

Other comments (areas of concern, wildlife sightings, trail markings and signage condition, need for re-route, possible encroachment):

Forward completed electronic form to: Dexter Robinson @ dexpcdoc@gmail.com