TRAIL ASSESSMENT FORM

Doc. #		Trail I	Name	Base Path South	Trail Type:	Wide -	Condition	Fair	
Route:		Trailhead on Chestnut Run Path – 1183 – 1185 – 1203 on Chestnut Run							
		Path							
			77 '11 11 1	. 1 1		D 1 107.6	. 011		
Recent Weather: TRAIL LANDMARKS			 Trailhead leaves the right side of Chestnut Run Path, 127 feet SW of the 1175 intersection marker on Border Path. Swale located at intersection with Eustis Trail to divert water toward small brook. Need to remove leaves. Eustis Trail leaves on the right at 81 feet. Overhead brushing at 100 feet for 120 feet. Moderate to Severe erosion ascending hill at 170 feet to .11 miles. Rockwork waterbar at 300 feet. L to R. Diverts water off trail but needs a good cleaning. Transition from area above waterbar to below is a drop of about three feet. Should use rock to make transition smoother. Moderate erosion continues above this waterbar. Erosion stops at .11 miles as treadway levels out. (1) Large tree (18") across trail at .12 miles. People going around it off trail. (2) Unnamed Trail leaves on left to Chestnut Run Path at intersection marker 1183 at .13 miles. Additional path leaves on left at this location not shown on map. Jeffries Trail leaves on right at .2 miles. Large fenced cistern on right side of trail at .20 miles. Minor erosion at .27 miles. 						
MINOR/ MAJOR PROBLEM			(1) Add stone at rockwork waterbar 300 feet from Marker 1175 end.Need to transition a three foot drop from top of trail to bottom.(2) Large tree (18") across trail at .12 miles.						
AREAS	S		,	B) Add stone at drop not foot drop from top of	ear Marker 1185	5. Need to	transition a th	nree	
DISTANCES TO		Chestnut Run Path trailhead to Eustis Trail – 81 Feet.							
MAJOR		• Chestnut Run Path trailhead to intersection marker 118313							
INTERSECTIONS									
			•	Chestnut Run Path t miles.				32	

		ailhead to the end of Base Path and its Chestnut Run Path at intersection marker
Report prepared by:	Bob Flagg	Assessment date: 12/21/15