

TRAIL ASSESSMENT FORM

Doc. #	Trail Name	Base Path Connector	Trail Type:	Footpath	Condition	Good
Route:		Border Path Marker 1165 to Chestnut Run Path Marker 1191				
Recent Weather:		Warm, 60's - melting snow and ice – Snow cover on trail less than 1 inch				
TRAIL LANDMARKS		<ul style="list-style-type: none"> • Trailhead leaves Border Path Marker 1165 heading south crossing side ditch along Border Path. • Trail crosses Eustis Path Marker 1166 at 200 feet. • Medium blowdown at 350 feet. • Trail crosses a stone wall at 425 feet. • Trail crosses small brook with stepping stones at 475 feet. • Base Path Marker 1183 crosses at 575 feet. • Trail ends at Chestnut Run Path marker 1191 at 750 feet. 				
MINOR&MAJOR PROBLEM AREAS		None				
DISTANCES TO MAJOR INTERSECTIONS		<ul style="list-style-type: none"> • Border Path Marker 1165 to Eustis Path Marker 1166 – 200 feet. • Border Path Marker 1165 to Base Path Marker 1183 – 575 feet. • Border Path Marker 1165 to Chestnut Run Path Marker 1191 – 575 feet. 				
Report prepared by:		Bob Flagg		Assessment date:		2/1/16