

TRAIL ASSESSMENT FORM

Doc. #		Trail Name	Border Path North from Hillside Street	Trail Type:	Wide - M	Condition	Good
Route:		Hillside St.- 1224 – 1215 – Unquity Rd. – 1175 – 1135 – 1114 – 1100 Walcott Path					
Recent Weather:		Sunny, some recent rain					
TRAIL LANDMARKS		<ul style="list-style-type: none"> • Trail leaves the north side of Hillside Ave., .2 miles northeast of the Hillside Street, Chickatawbut Road intersection. Trailhead is marked with two boulders. • Unnamed trail crosses at 240 feet. • Stream parallels trail at .11 miles and crosses at .12. Stream is about 8 feet wide. Culvert, stepping stones or bog bridge may be considered. No significant erosion noted. • Valley Path enters on left at intersection marker 1224 at .15 miles. • Small ditch crosses L to R at .16 miles. Clean • Rock wall on left w/ boundary marker at .27 miles. • Unnamed path leaves on right at gate at .32 miles. • Steel 10” culvert at .33 miles. All set • Plastic 10” culvert crosses trail at .40 miles. All set • Plastic 10” culvert crosses trail at .46 miles. All set • Massasoit Path leaves on right at intersection marker 1215 at .49 miles. Granite boundary marker at corner of fence on right. • Swale just past marker 1215 • Steel 8” culvert at .52. All set • Unquity Road crosses at .55 miles w/ fire gates on both sides of road. • Granite marker labeled Border Path on right when reentering woods. • Culvert under trail at .61 miles. L to R, 12” plastic. Ditch on left parallels road into Culvert. Inflow area is buried. Culvert was only functional at high water times. Need to decide if it should be cleaned out. • Culvert under trail just after .61 miles. L to R w/ rockwork wells on both sides. 18” plastic. Ditch on left parallels road on left into culvert. All set. • Culvert under trail just after last culvert above at .61 miles. Stream L to R with rockwork wells on both sides. Two pipes 18” and 24” plastic. Smaller culvert is half full with dirt and rocks. Clean. Cut logs in side ditch to push water thru two culverts with overflow continuing to next culvert. • Small trail leaves on right at .63 miles • Grade reversal at .65 miles. L to R. Ditch on right. Clean. • Nice fireplace at old home site on left at .66 miles. • Grade reversal at .67 miles. L to R. Ditch on right. Clean. • Grade reversal just after culvert at .67 miles. L to R. Ditch on right. Clean. • Unnamed trail leaves on right at .69 miles 					

	<ul style="list-style-type: none"> • Rd at .7 miles. R to L. Ditch on left. Clean. • Rd at .72 miles. R to L. Ditch on left. Clean. • Rd at .74 miles. R to L. Ditch on left. Clean. • Rd at .76 miles. R to L. Ditch on left. Clean. • Chestnut Run Path leaves on left at intersection marker 1175 at .79 miles. Unnamed trail leaves on right. • Yellow triangular blazes start at intersection. • Culvert under road at .83. R to L. Streambed, 20” dia. Rockwork well and ditch both sides. All set • Large ditch on left at start of hill at .83 to .87 miles into streambed. Clean. • Culvert 18” plastic under road at .85. R to L. Clean. • Grade reversal at .85 R to L into Culvert noted above. • Grade reversal at .86 L to R into ditch on right. Clean. • Culvert 8” plastic under road at .87 miles. L to R. Rockwork wells both sides. Clean. • Wooden waterbar at .87 miles 20 yards past Culvert. R to L into trench on left. • Eustis Trail Connector leaves on left at .87. • Start to lose large ditch on left from start of hill at .87 miles. • Stone enhanced wooden waterbar .89 L to R. width of trail. Ditch on right. All set. • RR tie waterbar at .89 miles. L to R into ditch on right. Clean. • Another RR tie .90 L to R into ditch on right. Clean. • Grade reversal at .92 miles L to R into ditch. All set • Bartol Path leaves on right and the Five Corners Path leaves on left at intersection marker 1135 at 1.03 miles. Trail now blazed w/ green dot. • Culvert under trail at 1.05 miles. Stream crossing. Rockwork wells both sides. 30” dia. Cement. Good shape. Clean. • Stone grade reversal crosses at 1.06 miles. L to R. Width of trail. Needs more dirt to cover rocks and dig out the outflow trench. Clean. • Wooden waterbar in another 10 yards. L to R. Clean. • Stone grade reversal at 1.07 miles. L to R. Ditch on right. Needs more dirt to cover rocks and dig out the outflow trench. Clean. • Three Wooden waterbars at 1.08 to 1.09. L to R. Pretty minimal flow but should dig out a bit to enhance flow. Clean. • Rotch Path leaves on left at intersection marker 1114 at 1.10 miles. • Culvert at this intersection for stream. L to R. 30” cement with rockwork on R and L. • Carberry Path leaves on right at 1.26 miles. • Wooden waterbar just before intersection but the outflow slopes uphill. Outflow would require serious digging to reestablish. Probably not worth the effort to open and keep open. • Border Path ends as it intersects Wolcott Path at intersection marker 1100 at 1.26 miles
MINOR/ MAJOR PROBLEM	None

AREAS			
DISTANCES TO MAJOR INTERSECTIONS	<ul style="list-style-type: none"> • Hillside Street to Valley Path marker 1224 - .15 miles. • Hillside Street to Unnamed path at marker 1215 - .49 miles. • Hillside Street to Unquity Road - .55 miles • Hillside Street to Chestnut Run Path at marker 1175 - .79 miles. • Hillside Street to Bartol Path /Five Corners Path at marker 1135 - 1.03 miles. • Hillside Street to Rotch Path at marker 1114 - 1.08 miles. • Hillside Street to Wolcott Path at marker 1100 - 1.26 miles 		
Report prepared by:	Bob Flagg	Assessment date:	12/25/15