

TRAIL ASSESSMENT FORM

| | | | | | | | |
|---|---|-------------------|---------------------|-------------------------|------------|------------------|------|
| Doc. # | | Trail Name | Brookwood Farm Road | Trail Type: | Paved Road | Condition | Good |
| Route: | Starting at western intersection with Blue Hill River Road and continuing around Conference Center to eastern intersection | | | | | | |
| Recent Weather: | Sunny, 45°F, all day rain on previous day | | | | | | |
| TRAIL LANDMARKS | <ul style="list-style-type: none"> • 22ft beginning of parking, ends at 119ft • 400ft building complex with small gravel road to left • 0.19mi left turn to road behind conference center <ul style="list-style-type: none"> ○ This road has no issues • 0.21mi Intersection 1057 • 0.25mi parking area • 0.32mi Intersection 1077 • 0.5mi trail meets with Blue Hill River Road | | | | | | |
| MINOR PROBLEM AREAS | | | | | | | |
| MAJOR PROBLEM AREAS | | | | | | | |
| DISTANCES TO MAJOR INTERSECTIONS | <ul style="list-style-type: none"> • 0ft Blue Hill River Road • 0.19mi branch off behind conference center • 0.21mi Intersection 1057 with Conference Center trails • 0.32mi Intersection 1077 with Conference Center trails • 0.50mi Ends at Blue Hill River Road | | | | | | |
| Report prepared by: | Robert Shine | | | Assessment date: | 10-23-2016 | | |