## TRAIL ASSESSMENT FORM

Doc. # Trail Na	ne Brookwood Trail Trail Type:	Narrow Condition Good
Route:	Hillside Ave. – 1062 – Wildcat Notch Path	
<b>Recent Weather:</b>	Drizzly, 50's, 1" of rain last night	
TRAIL	• Trailhead is located on the north side of Hillside Street approximately	
LANDMARKS	3/8 of a mile west of the Hillside Street, Blue Hills River Road	
	intersection.	
	<ul> <li>Trailhead is fairly hidden from the street however opens to a footpath once into the woods. Trailhead should be marked. Located across the street 300 feet from the Brookwood Road.</li> <li>Accord Path Marker 1062 crosses at 307 feet. There is a ditch that</li> </ul>	
	collects water from Brookwood Trail and moves it across Accord Path.	
	• Series of stone waterbreaks heading up the hill starting at 350 feet.	
	Stone waterbar, R to L, at .1 miles. Clean and improve.	
	• Stone waterbar, L to R at .18 miles. Clean.	
	• Series of stone waterbreaks at .19 miles.	
	• Rock walls on L and R at .20 miles.	
	• Wooden waterbar, L to R, at .22 miles. Clean.	
	Brookwood Trail ends at intersection with the Wildcat Notch Path just	
	south of the Marker 1083 at .41 miles. Swale collects water from	
	Brookwood Trail and moves it across Wildcat Notch Path.	
MINOR&MAJOR	None	
PROBLEM		
AREAS		
DISTANCES TO	Hillside Street Trailhead to Accord Path Marker 1062 – 307 feet.	
MAJOR	• Hillside Street Trailhead to Wildcat Notch Path41 miles.	
INTERSECTIONS		
Report prepared by:	Bob Flagg Assessn	nent date: 2/4/16



## **Abbreviations:**

ditches (dt)

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb) small blowdowns (sbd) culverts(cv) large blowdowns (lbd) rolling dips (rd) rock work (rkw) bridges (br) bridge building (bbd), bog bridges (bb) culvert replacement (cr) rock stairs (rs) trail relocation (tr), cribbing (cb) building new trail drainage (ntd) brushing needed (bn) retaining walls (rw)

excessive erosion (ee) leaning tree (lt)