TRAIL ASSESSMENT FORM

Doc. # Trail Na	ame Dalton Path North Trail Type: Footpath Condition Good
Route:	1117 to Wildcat Notch Path
Recent Weather:	Overcast. Partial snow coverage up to 1" on treadway.
TRAIL	Trailhead leaves the northwest side of the Skyline Trail North at
LANDMARKS	 intersection marker 1117. Treadway leaves the trailhead ascending slightly. Spur path leaves on the left (SW) at 66 feet back to the Skyline Trail
	North.
	• Treadway levels out at 150 feet then begins descending.
	• Treadway enters a gully with standing water from a pond to the left of the treadway at 200 feet. Trail is dry due to low level in pond. Stepping stones along side of trail. Water will flow across trail when level rises in pond.
	Treadway begins ascending out of the gully at footpath width.
	 Treadway begins descending moderately at 520 feet with minor erosion.
	Treadway reopens to road width at .11 miles.
	• Treadway enters an area for overflow of pond but no standing water from pond to the left (SW) of the treadway at .13 miles.
	• Treadway enters and ends with its intersection with the Wildcat Notch Path at .13 miles. Intersection is blazed with a small rock cairn at this
MINODOMATOD	location and mountain biking signage on tree is damaged. None
MINOR&MAJOR	NOTE
PROBLEM	
AREAS	
DISTANCES TO	Trailhead to Wildcat Notch Path13 miles.
MAJOR	
INTERSECTIONS	
Report prepared by:	Bob Flagg Assessment date: 1/29/16