TRAIL ASSESSMENT FORM

Doc.#	Trail Nan	ne Eustis Tra	il Trail Type:	Narrow Trail	Condition	Good
D4	E:	va Caman Dath	::::::::::::::::::::::::::::::::::::::	Daga Dath		
Route: Recent Weather:		Five Corner Path intersection 1140 – Base Path Worm 60's malting snow and ica. Snow gover on trail less than 1 inch.				
		Warm, 60's - melting snow and ice – Snow cover on trail less than 1 inch				
TRAIL LANDMARKS		 Trail leaves on the right from the Five Corners Path at Marker 1140. Trail starts at 4' wide. Trail turns into riverbed at .15 miles. At this point rockwork diverts traffic off to the left side of the erosion. There are some timbers in the erosion for soil stability. From this point through to .18 miles, the treadway in many areas continues as a riverbed with numerous sections of the trail paralleling the erosion on the left. Grade reversal, R to L, at .16 miles removing water from treadway. Needs cleaning. Grade reversal, R to L, at .17 miles removing water from treadway. Needs cleaning. Stone enhanced grade reversal with waterbar at .18 miles R to L. Trail rejoins the path at .18 miles. 				
		 Trail again enters an erosion area just beyond .20 miles similar to the last section with the trail paralleling the erosion on the left. Base Path Connector Marker 1166 crosses at .23 miles. Stone enhanced grade reversal, R to L, just beyond .23 miles diverts water off the trail on the left. Waterbar, R to L, at .24 miles. Clean. Stone enhanced grade reversal, R to L, at .27 miles. Stone enhanced grade reversal, R to L, .28 miles. Seep on trail. Needs cleaning. Ditch across trail at .30 miles. R to L and ditch into woods. Needs cleaning. Large culvert with rockwork surround on both sides, 30" cement, R to L, for stream at .30 miles. Outflow area on left full of debris, need good cleaning at low water. 				
MINOR&MAJOR (1) Clean outflow area of culvert at end of trail. Should be done when low flow of water.						when
PROBLEM		low flow	of water.			
AREAS						
DISTANCES MAJOR		 Five Corner Path Marker 1140 to Base Path Connector Marker 116623 miles. Five Corner Path Marker 1140 to Base Path31 miles. 				
INTERSECTIONS						
Report prepare	d by:	Bob Flagg		Assessment date	e: 2/1/16	