

TRAIL ASSESSMENT FORM

Doc. #		Trail Name	Massasoit Path	Trail Type:	Wide	Condition	Good
Route:	North from Intersection 1215 on Border path roughly parallel with Unquity Rd						
Recent Weather:	Sunny, 45°F, all day rain on previous day						
TRAIL LANDMARKS	<ul style="list-style-type: none"> • 34ft old grade reversal but could use some work • Some brushing • 196ft old culvert (left to right flow) good flow through path, but could use a cleaning – can't tell composition/size of culvert • 0.42mi – 12in clay culvert – some cleaning needed • 0.56mi ends at Unquity Rd 						
MINOR PROBLEM AREAS	<ul style="list-style-type: none"> • Some brushing needed, especially around 0.14mi • Grade reversal touch up at 34ft – better trench and outflow • Culvert at 0.42mi needs cleaning on both ends of pipe 						
MAJOR PROBLEM AREAS	<ul style="list-style-type: none"> • Culvert at 196ft needs more thorough examination to determine condition but at least needs to be cleaned 						
DISTANCES TO MAJOR INTERSECTIONS	<ul style="list-style-type: none"> • 0ft Intersection 1215 – Border Path • 0.56mi – Trail ends at Unquity Rd 						
Report prepared by:	Robert Shine			Assessment date:	10-23-2016		