## TRAIL ASSESSMENT FORM

MINOR	<ul> <li>Coon Hollow and Puddle Paths cross at 1092 at 1.26 mile</li> <li>Small wb and dt as Skyline North intersect these trails at 1.26 mile and will require cleaning.</li> <li>Rkw and rw just after trail intersection ascending Great Blue Hill will require bn</li> <li>Marker 1092 (8)</li> <li>Elliot Circle crosses at 1063 at 1.17 miles</li> <li>(1) Minor erosion due to increased treadway. Additional Blazing</li> </ul>		
	recommended.		
PROBLEM			
AREAS	(2) Minor erosion due to increased treadway. Should be reviewed.		
	(3) Minor erosion due to increased treadway. Possibly block side trail?		
	<ul> <li>(4) Minor erosion due to increased treadway. Should be reviewed.</li> <li>(5) Minor erosion due to increased treadway. Should be reviewed.</li> <li>(6) Increased treadway. Possible bog bridge location.</li> <li>(7) SBD on side of trail. No issue however blaze on it needs relocation.</li> </ul>		
	(8) Marker is missing in the field		
MAJOR	None noted, Trail is a strenuous trail with many areas requiring significant		
PROBLEM	scrambling. Addressing these areas for safety sake I believe would detract		
AREAS	from this trails appeal.		
	~ -		
DISTANCES TO	Hillside Street to Breakneck Ledge Path (1162) – .52 Miles		
MAJOR	Hillside Street to Walcott and Five Corners Paths (1141) – .84 Miles		
INTERSECTIONS		Vildcat Notch Path R (1117) – 1.00 Miles	
	Hillside Street to Coon Hollow and Puddle Paths (1092) – 1.26 Miles		
	Hillside Street to – Elliot Circle (1063) - 1.47 Miles		
Report prepared by:	Ken Jones	Assessment date:	11/26/2007

## **Abbreviations:**

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb) small blowdowns (sbd)
culverts(cv) large blowdowns (lbd)
rolling dips (rd) rock work (rkw)
bridges (br) bridge building (bbd),
bog bridges (bb) culvert replacement (cr)
rock stairs (rs) trail relocation (tr),

cribbing (cb) building new trail drainage (ntd)

retaining walls (rw) brushing needed (bn) ditches (dt) excessive erosion (ee)

leaning tree (lt)