TRAIL ASSESSMENT FORM

Doc.#	# 1010 Trail N		lame	Rotch Path South	Trail Type:	Wide Trail - H	Condition	Good
Route:			Border Path marker 1114 to Wolcott Path intersection					
Recent Weather:			Snow 12/2, Currently light rain and mist – Partial snow coverage up to 1 inch on trail					
TRAIL			Trailhead leaves Border Path at Intersection marker 1114.					
LANDMARKS			Bn required from start and many additional areas along route.					
·			 Hemenway Hill Path leaves on left at .13 miles. 					
			• Minor sbd in trail at .19 miles.					
			• Cv under trail at .2 miles. Stream. Cement 18" pipe. Nice rkw on left.					
			Poor dt on right. Pipe halfway full.					
			• Rotch Path ends with its intersection with Wolcott Path at .23 miles					
MINOR		Blowdown, brushing and cleaning required.						
PROBLEM								
AREAS								
MAJOR			None noted					
PROBLEM								
AREAS								
DISTANCES TO			Border Path to Hemenway Hill Path13 miles					
MAJOR			Border Path to Wolcott Path23 miles					
INTERSECTIONS								
Report prepared by:			K	en Jones		Assessment date	: 12/10/20	07

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)small blowdowns (sbd)culverts(cv)large blowdowns (lbd)rolling dips (rd)rock work (rkw)bridges (br)bridge building (bbd),bog bridges (bb)culvert replacement (cr)rock stairs (rs)trail relocation (tr),

cribbing (cb) building new trail drainage (ntd)

retaining walls (rw) brushing needed (bn) ditches (dt) excessive erosion (ee)

leaning tree (lt)