TRAIL ASSESSMENT FORM

Doc. #	1012	Trail	Name	Breakneck Ledge Path North (rev.1)	Trail Type:	Wide - M	Condition	Good	
Route: Recent Weather: TRAIL LANDMARKS									
MINO PROB AREA	LEM		.38 • He .41 • Tr • Br • Cv wi • Cv co • Ov • Br int (1) Re (2) Tv	miles. menway Hill Path lead miles. eadway continues at rota at .46 miles. crosses under treadway th corrugated 24" pipe crosses under treadway erhead and side Bn at eakneck Ledge path ertersection marker 1185 with dt on right with a vo very lbd cross tread quires, as this is a fire reserved.	ves on right (early at .48 miles.). Clean dt both ay at .49 miles in ated 24" pipe. Co.50 miles. Inds with it's into at .53 miles. Ibd in dt blockinway at .23 mile	st) at intersection at .43 miles. In streambed. Clean dt both ersection with a grown at 26 s. 6-24" Cha	es. /earthen cons . R to L. Rkw sides. h Base path a	truction /earthen tt	
MAJO PROBI AREA DISTA MAJO INTER S	LEM <u>S</u> NCES R		 Wolcott Path marker 1160 to Skyline North intersection marker 11621 miles. Wolcott Path marker 1160 to Hemenway Hill Path enters at intersection marker 1178 at .38 miles. Wolcott Path marker 1160 to Hemenway Hill Path leaves at intersection marker 1180 at .41 miles. 						

	•	• Wolcott Path marker 1160 to Breakneck Ledge Paths ends with its intersection with the Base Path at intersection marker 118553 miles.					
Report prepared by:		Ken Jones Rev1. 4/3/08	Assessment date:	1/7/2008			





BNL2



Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb) small blowdowns (sbd) culverts(cv) large blowdowns (lbd)

rolling dips (rd) rock work (rkw)
bridges (br) bridge building (bbd),
bog bridges (bb) culvert replacement (cr)
rock stairs (rs) trail relocation (tr),

cribbing (cb) building new trail drainage (ntd)

retaining walls (rw) brushing needed (bn) ditches (dt) excessive erosion (ee)

leaning tree (lt)