

TRAIL ASSESSMENT FORM

Doc. #	1033	Trail Name	Unnamed Trail 1215 North	Trail Type:	Wide – M	Condition	Good
Route:		1215 – Unquity Road/Harland Street Intersection					
Recent Weather:		Cloudy in the 50's with light rain. Rain in last 24					
TRAIL LANDMARKS		<ul style="list-style-type: none"> The trailhead is located on the east side of Border Path, 300 feet east of Unquity Road at intersection marker 1215. <ul style="list-style-type: none"> Although the location of this trail is shown on the latest (9/09) DCR map, it is still shown as an unnamed trail. Trailhead leaves from intersection marker 1215 at road width. There is a granite marker and a chain link fence located just to the right of the treadway. Dip in the treadway at 30 feet. R to L with a dt on the left. Treadway is reduced to footpath width at 100 feet. Bn at 150 feet. Cv under the treadway 200 feet. 15" steel pipe. No issues. Unnamed path leaves on the right at path width. Overhead bn at .19 miles. Pine boughs. Treadway enters a wetland area at .29 miles with marshes on both sides and runoff in the treadway. Possible bog bridge location. (1) Cv under the treadway .33 miles. 15" steel pipe. No issues. Overhead bn at .44 miles. Pine boughs. Boy Scout Camp noted to the left on the other side of Unquity Road. Lbd crosses the treadway at .47 miles. Can be stepped over. Treadway narrows at .53 miles, turns slightly left and begins to ascend up onto a large berm (pipeline) beside and higher than Unquity Road. Treadway passes through two telephone pole diameter markers across from the Egan Center at .55 miles. At this point the treadway opens to 20 feet and is mowed grass. Unnamed Trail 1033 ends at a river not shown on the DCR map at .65 miles. There is a fenced in concrete water control structure at this point with a small picnic and parking area. This is located at the intersection of Unquity Road and Harland Streets. 					
MINOR PROBLEM AREAS		1. Treadway enters a wetland area at .29 miles with marshes on both sides and runoff in the treadway. Possible bog bridge location. (1)					
MAJOR PROBLEM AREAS		None Noted					
DISTANCES TO MAJOR INTERSECTIONS		Trailhead at 1215 to Unquity Road/Harland Street Intersection - .65 miles					
Report prepared by:		Ken Jones – 11/27/2009		Assessment date:		11/24/2009	

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)
culverts(cv)	large blowdowns (lbd)
rolling dips (rd)	rock work (rkw)
bridges (br)	bridge building (bbd),
bog bridges (bb)	culvert replacement (cr)
rock stairs (rs)	trail relocation (tr),
cribbing (cb)	building new trail drainage (ntd)
retaining walls (rw)	brushing needed (bn)
ditches (dt)	excessive erosion (ee)
leaning tree (lt)	