TRAIL ASSESSMENT FORM

Doc. # 3014 Trail N	Name Slide Notch Path Trail Type: M Condition Good
Doutes	ml:2072 at DDT to Chiele Dd just heleve the Overleek
Route:	mk3073 at BBT, to Chick Rd, just below the Overlook
Recent Weather:	Light snow ¼"-1" 33F. A few inches of rain has fallen last few days.
TRAIL	Trail starts as a steep rocky tread with waterflow
LANDMARKS	40 yd nf wb(1)
	50.4 yd nf wb dt(2)
	$60 \text{ yd } \underline{2} \text{ nf wbs}(3)$
	90 yd fc rd
	127 yd stream enters trail
	238 yd , 247 yd, nf wbs(4)
	257 yd stream crosses trail L to R(5)
	315 yd stream crosses R to L(5)
	346 yd sbd, bn(6)
	409 yd mk 3093 int w/Skyline
	436 yd nf wb(7)
	460 yd mk3090
	trail still very wet
	585 yd rock 'steps' going downslope until 602 yd
	612 yd nf rk wb(8)
	626 yd trail 'splits', presumably at mk3096(9) follows left to Chick Rd.
	700 yd trail ends at Chick Rd.
MINOR	(1) -1
MINOR	(1)cleanout wb
PROBLEM	(2)cleanout wb and dt
AREAS	(3) cleanout wbs
	(4) cleanout wbs
	(5) stream crossings not really harming the trail at these points as it is
	fairly rock-armored
	(6)trail saw, loppers, crew of 3
	(7) cleanout wb
	(8) cleanout wb
	(9)no mk,, replace
MAJOR	Given the amount of waterbar and ditch cleanouts needed, and the amount
PROBLEM	of use this trail gets, it should be of a higher priority, and will require many
AREAS	hours of digging and raking to complete.
DISTANCES TO	409 yd from mk3073 at BBT to mk3093 at Skyline, 700 yd. to Chick Rd.
MAJOR	
INTERSECTIONS	
Report prepared by:	Steve Cobble Assessment date: 02/02/08

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)small blowdowns (sbd)culverts(cv)large blowdowns (lbd)rolling dips (rd)rock work (rkw)

bridges (br) bridge building (bbd), ditches (dt) corrugated plastic(cp)

excessive erosion (ee) leaning tree (lt)) intersection marker(mk) dugout(du)

bog bridges (bb) culvert replacement (cr)

non-functioning(nf) functioning(fc)

damage(dg) not needed(nn) cm (corrugated metal)

rock stairs (rs) trail relocation (tr),

cribbing (cb) building new trail drainage (ntd)

retaining walls (rw) brushing needed (bn)

clay(cl)