

# TRAIL ASSESSMENT FORM

<b>Doc. #</b>	3022	<b>Trail Name</b>	Lee Path	<b>Trail Type:</b>	M	<b>Condition</b>	Good
<b>Route:</b>		From Bouncing Brook Trail (BBT )at mk3070 heading generally SW to mk3055 at Braintree Pass Path(BPP)					
<b>Recent Weather:</b>		Clear, rain earlier in week					
<b>TRAIL LANDMARKS</b>		Mk3070 trail begins at BBT 10yd fc cv 270yd lt(1) 370yd nf dt and nf 12" cl cv(2) 390yd some washout (3) 410yd int w/Braintree Pass Path					
<b>MINOR PROBLEM AREAS</b>		(2)cleanouts (3) recommend some drainage correction of the waterflow coming off BPP. This washout may be due to a hidden nf cv on BPP. Recommend investigation					
<b>MAJOR PROBLEM AREAS</b>		(1)chainsaw crew					
<b>DISTANCES TO MAJOR INTERSECTIONS</b>		410yd total from mk3070 to mk3055					
<b>Report prepared by:</b>			Steve Cobble		<b>Assessment date:</b>		03/10/08

## Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)	
culverts(cv)	large blowdowns (lbd)	
rolling dips (rd)	rock work (rkw)	
bridges (br)	bridge building (bbd), ditches (dt)	corrugated plastic(cp)
excessive erosion (ee)	leaning tree (lt))	
intersection marker(mk)	dugout(du)	
bog bridges (bb)	culvert replacement (cr)	
non-functioning(nf)	functioning(fc)	
damage(dg)		
not needed(nn)		
cm ( corrugated metal)		
rock stairs (rs)	trail relocation (tr),	
cribbing (cb)	building new trail drainage (ntd)	
retaining walls (rw)	brushing needed (bn)	
clay(cl)		