

TRAIL ASSESSMENT FORM

Doc. #		Trail Name	Quincy Path	Trail Type:	Narrow	Condition	Good
Route:	Heading E to W along the S side of Chickatawbut Rd, closest Marker is 2153.						
Recent Weather:	Overcast, 40's, rain a few days ago						
TRAIL LANDMARKS	<ul style="list-style-type: none"> • Trail begins at Chickatawbut Rd. There is a granite marker indicating Headquarters Path at roadside. Headquarters Path actually crosses the road and continues on the North side of Chickatawbut Rd. The path that runs along the South side of the road is Quincy Path. • Trail passes through a perennially wet, rocky section, then sharply uphill. • .17 mi stream crossing under four foot planked wooden bridge. • .21 mi Barre Trail crosses • .26 mi perennially wet area overtaking the trail—investigate the possibility of re-routing the trail to the right, to higher ground, for approx. 20 yds. • .27 mi Bridge crosses small brook and wetland area. Bridge was replaced in 2017. Bridge is 2 x 6' planks, approx. 70 feet long and three foot wide. • .31 mi Dark Hollow Path Marker 2112 crosses. Fire gate at location along with granite post marked Dark Hollow Path. Green Dot Trail and white multi-use arrows join trail from Dark Hollow Path. • .32 trail enters another wet area about 40 feet long. Section could use some kind of basic bridge to cross wet area. Trail narrows and steepens sharply up technical climb. • .35 mi Actual route for Headquarters Path rejoins trail from North side of road. Granite post located at roadside marked Headquarters Path. 						
MINOR&MAJOR PROBLEM AREAS	Should review possible bridges at two wet areas.						
DISTANCES TO MAJOR INTERSECTIONS	<ul style="list-style-type: none"> • From Chickatawbut Rd to Barre Trail - .21 mi. • From Chickatawbut Rd to Dark Hollow Path Marker 2112 - .31 mi. • From Chickatawbut Rd to Headquarters Path - .35 mi. 						
Report prepared by:	Bob Flagg			Assessment date:	1/6/20		