

TRAIL ASSESSMENT FORM

Doc. #	2006	Trail Name	Fells Path	Trail Type:	M(MTB)	Condition	Good
Route:		From mk2152 at Buck Hill Trail, heading generally S, to mk 2140 at Bugbee Path					
Recent Weather:		Clear, no recent precip					
TRAIL LANDMARKS		Wide trail begins at mk2152, Buck Hill Trail. Perennially wet area. 10yd cv empties onto the trail on L(1) 150yd du 302yd mk2149 int w/ Pig Rock Path. Trail bears right. 474yd mk2140 trail ends at Bugbee Path					
MINOR PROBLEM AREAS		(1) possibly rkw to alleviate muddy section					
MAJOR PROBLEM AREAS							
DISTANCES TO MAJOR INTERSECTIONS		474yd from mk2152 to mk2140					
Report prepared by:			Steve Cobble		Assessment date:		03/24/08

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)	
culverts(cv)	large blowdowns (lbd)	
rolling dips (rd)	rock work (rkw)	
bridges (br)	bridge building (bbd), ditches (dt)	corrugated plastic(cp)
excessive erosion (ee)	leaning tree (lt))	
intersection marker(mk)	dugout(du)	
bog bridges (bb)	culvert replacement (cr)	
non-functioning(nf)	functioning(fc)	
damage(dg)		
not needed(nn)		
cm (corrugated metal)		
rock stairs (rs)	trail relocation (tr),	
cribbing (cb)	building new trail drainage (ntd)	
retaining walls (rw)	brushing needed (bn)	
clay(cl)		
MTB(mountainbikes allowed)		
(mk2042) meaning not on DCR map		