

TRAIL ASSESSMENT FORM

Doc. #	2007	Trail Name	Pig Rock Path	Trail Type:	M(MTB)	Condition	Good
Route:		From mk2149 at Fells Path, heading generally E, to mk 2172 at Bugbee Path					
Recent Weather:		Clear, no recent precip					
TRAIL LANDMARKS		Trail begins at mk2149, int w/ Fells Path 176yd mk2154 Fern Spring Foot Path bn 580yd mk2172(1) end of trail at Bugbee					
MINOR PROBLEM AREAS		(1) replace worn mk					
MAJOR PROBLEM AREAS							
DISTANCES TO MAJOR INTERSECTIONS		From mk2149 to mk2172, 580yd					
Report prepared by:			Steve Cobble		Assessment date:		03/24/08

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb) culverts(cv) rolling dips (rd) bridges (br) excessive erosion (ee) intersection marker(mk) bog bridges (bb) non-functioning(nf) damage(dg) not needed(nn) cm (corrugated metal) rock stairs (rs) cribbing (cb) retaining walls (rw) clay(cl) MTB(mountainbikes allowed) (mk2042) meaning not on DCR map	small blowdowns (sbd) large blowdowns (lbd) rock work (rkw) bridge building (bbd), ditches (dt) leaning tree (lt)) dugout(du) culvert replacement (cr) functioning(fc) trail relocation (tr), building new trail drainage (ntd) brushing needed (bn)
-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

corrugated plastic(cp)