

# TRAIL ASSESSMENT FORM

<b>Doc. #</b>	2011	<b>Trail Name</b>	Beech Hollow Path	<b>Trail Type:</b>	M(MTB)	<b>Condition</b>	Good
<b>Route:</b>		From mk2135 to mk 2146, heading generally south					
<b>Recent Weather:</b>		Clear and unseasonably dry					
<b>TRAIL LANDMARKS</b>		Wide trail begins at mk2135 at Bugbee Path, part of the white arrow MTB loop(traveling opposite direction today) 278yd mk2132, int with Doe Hollow on right(white arrow MTB loop coming in at this point) 352yd trail bears left. Option to continue to Old Rte 128 on no name connector at this point. There is a mk2123 on the DCR map, and is associated with the int of this connector and Old Rte 128, where there is a mk 556yd mk2146 trail ends at in with Oblique and Old Rte.128					
<b>MINOR PROBLEM AREAS</b>		No drainage issues No brushing needed					
<b>MAJOR PROBLEM AREAS</b>							
<b>DISTANCES TO MAJOR INTERSECTIONS</b>		From mk2135 278yd to mk2132 556yd to mk2146, trail end					
<b>Report prepared by:</b>			Steve Cobble		<b>Assessment date:</b>		04/18/08

## Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb) culverts(cv) rolling dips (rd) bridges (br) excessive erosion (ee) intersection marker(mk) bog bridges (bb) non-functioning(nf) damage(dg) not needed(nn) cm ( corrugated metal) rock stairs (rs) cribbing (cb) retaining walls (rw) clay(cl) MTB(mountainbikes allowed) (mk2042) meaning not on DCR map	small blowdowns (sbd) large blowdowns (lbd) rock work (rkw) bridge building (bbd), ditches (dt) leaning tree (lt)) dugout(du) culvert replacement (cr) functioning(fc)  trail relocation (tr), building new trail drainage (ntd) brushing needed (bn)
---	--

corrugated plastic(cp)