TRAIL ASSESSMENT FORM

Doc. #	2016	Trail Nam	e Bolton Foot Path (FBH)	Trail Type:	(H)	Condition	Good		
Route:			East to West from the White Loop along the Doe Hollow dogleg before mk2132, to the southern end of Angle Path						
Recent Weather:			Clear and dry						
TRAIL			No mk at either end						
LANDMARKS			'No bike' signage Some brushing needed, but not imperative. 257 yd to end						
MINOR									
PROBLEM									
AREAS									
MAJO	R								
PROB	LEM								
AREA	S								
DISTANCES TO		TO 25'	257 yd total						
MAJO	R								
INTER	SECT	IONS							
Report prepared by:		d by:	Steve Cobble	Asses	sment date	: 05/12/08	3		

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)						
culverts(cv)	large blowdowns (lbd)						
rolling dips (rd)	rock work (rkw)						
bridges (br)	bridge building (bbd), ditches (dt)	corrugated plastic(cp)					
excessive erosion (ee)	leaning tree (lt))						
intersection marker(mk) dugout(du)							
bog bridges (bb)	culvert replacement (cr)						
non-functioning(nf)	functioning(fc)						
damage(dg)							
not needed(nn)							
cm (corrugated metal)							
rock stairs (rs)	trail relocation (tr),						
cribbing (cb)	building new trail drainage (ntd)						
retaining walls (rw)	brushing needed (bn)						
clay(cl)							
MTB(mountainbikes allowed)							
(mk2042) meaning not on DCR map							