

TRAIL ASSESSMENT FORM

Doc. #	2020	Trail Name	Andover Path	Trail Type:	M	Condition	Good
Route:		From southernmost end of Tucker Hill Path eastward to Burnt Hill Path					
Recent Weather:		Cool and dry					
TRAIL LANDMARKS		Trailhead is located off of the green dot loop by Breeze Hill, just before the road becomes paved, (southernmost end of Tucker Hill Path). Single-track footpath. 474 ft. newly constructed 50 ft. bog bridge over a perennially wet area. 0.14 m. intersection with unnamed trail on the right. 0.15 m. sbd 0.16 m. moderate ascent. Trail widens a bit here. 0.21 m. trail descends to wet area. 0.23 m. turnpike over wet area. (1) 0.25 m. trail end at intersection with Burnt Hill Path					
MINOR PROBLEM AREAS		(1) Potential for standing water during heavy rain.					
MAJOR PROBLEM AREAS		None					
DISTANCES TO MAJOR INTERSECTIONS		0.14 m. trailhead to unnamed trail 0.25 m. trailhead to trail end at Burnt Hill Path					
Report prepared by:			Caleb Blankenship		Assessment date:		11/6/11

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)
culverts(cv)	large blowdowns (lbd)
rolling dips (rd)	rock work (rkw)
bridges (br)	bridge building (bbd),
bog bridges (bb)	culvert replacement (cr)
rock stairs (rs)	trail relocation (tr),
cribbing (cb)	building new trail drainage (ntd)
retaining walls (rw)	brushing needed (bn)
ditches (dt)	excessive erosion (ee)
	leaning tree (lt)

V5 NDR