TRAIL ASSESSMENT FORM

Doc. # 2043	Trail N	Vame	Old Route 128	Trail Type:	M (Condition	Good
	•			, , ,	•		
Route:		Houghtons Pond Athletic Field gate to Monatiquot Path					
Recent Weather:		Warm (mid 30s), dry last few days, bare ground					
TRAIL		Trailhead is located at the gate at the end of the road that leads to					
LANDMAR	RKS	•	the Athletic Fields n for Route 128. Trail leaves from La Roadbed of asphalts Cv crossed under ro- concrete cv. Need to	at 507 feet and rustarts at 537 feet. ad at .16 miles. I	ns toward Ho	oughton's F	ond.
		 concrete cv. Need to clean inflow and outflow areas to improve flow. Side trail at marker 2085 at .31 miles. Cv at .36 miles (relatively dry) probably flows at high water. Need 					
		 Cv at .36 lines (relatively dry) probably flows at high water. Need light cleaning. Angle Path enters L at marker 2100 at .47 miles. Handmade marker reading 2010 placed at site. DCR notified to replace sign. Brook flowing through cv at .69 miles. 18" concrete cv. Needs light cleaning. 					
		•	Side trail at marker 2 Beech Hollow Path along the side of roa Oblique Path enters Trail ends at intersect miles. It appears thi the old roadbed. The	enters L at markedway. at marker 2150 action with pipelings is where the ne	or 2146 at .78 t .88 miles. te and Monati w roadbed ru	quot Path a	at 1.00
MINOR PROBLEM AREAS		Trail has many trees growing over the road that need to be trimmed back. There are two large oak trees across part of the road toward the pipeline end of road. Culverts need a good general cleaning.					
MAJOR		None					
PROBLEM							
AREAS							
DISTANCES TO		○ Side trail marker 2085 at .31 miles					
MAJOR		 Angle Path at marker 2100 at .47 miles 					
INTERSECTIONS		 Side trail marker 2123 at .70 miles 					
	o Beech Hollow Path at marker 2146 at ./8 miles						
D		0	Oblique Path at ma			0/20/11	
Report prepar	red by:	Bo	ob Flagg & Robert S	hine Asses	sment date:	2/20/12	

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)small blowdowns (sbd)culverts(cv)large blowdowns (lbd)rolling dips (rd)rock work (rkw)bridges (br)bridge building (bbd),

bog bridges (bb) rock stairs (rs) cribbing (cb) retaining walls (rw) ditches (dt) culvert replacement (cr) trail relocation (tr),

building new trail drainage (ntd) brushing needed (bn)

excessive erosion (ee)

leaning tree (lt)

V5 NDR