TRAIL ASSESSMENT FORM

Doc. # 6006 Trail Na	ame Orchard Trail South Trail Type: Wide - M Condition Good
,	
Route:	6104 – Green Hill Trail
Recent Weather:	Moderate rain in last 24 hours – Sunny and 32 degrees
TRAIL	• Trailhead leaves the Green Hill Trail at intersection marker 6104 at road
LANDMARKS	width.
	• Bn at 299 feet. Side and overhead. Pine boughs extending into the
	treadway.
	 Treadway begins ascending slightly at 200 feet.
	• Bn at 440 feet. Side and overhead. Pine boughs extending into the
	treadway.
	• Bn at .11 miles. Saplings extending into the treadway.
	• Bn at .14 miles feet. Saplings extending into the treadway.
	• Treadway gets rutty due to runoff at .17 miles.
	 Treadway begins ascending slightly at .17 miles.
	• Treadway continues ascending slightly again at .19 miles.
	• Bn at .22 miles as treadway turns hard right (SW) at the park boundary.
	• The Brown Path leaves on the left at .27 miles at road width.
	Additional spur trail to Brown Path at road width noted on the DCR
	map does not exist in the field.
	• Bn at .3 miles.
	• The Orchard Trail ends with its intersection with the Green Hill path at
MINOD	.33 miles.
MINOR	• None noted
PROBLEM	
AREAS	
MAJOR	• None noted
PROBLEM	
AREAS	
DISTANCES TO	• Orchard Trail trailhead intersection marker 6104 to the Green Hill Trail
MAJOR	33 miles
INTERSECTIONS	
Report prepared by:	Ken Jones – 12/20/2008 Assessment date: 12/18/2008

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb) small blowdowns (sbd)
culverts(cv) large blowdowns (lbd)
rolling dips (rd) rock work (rkw)
bridges (br) bridge building (bbd),
bog bridges (bb) culvert replacement (cr)
rock stairs (rs) trail relocation (tr),

cribbing (cb) building new trail drainage (ntd)

retaining walls (rw) brushing needed (bn)

ditches (dt) excessive erosion (ee) leaning tree (lt)