TRAIL ASSESSMENT FORM

Doc. #	5008	Trail N	lame	No Name Path West	Trail Type:	Wide - M	Condition	Good	
Route:			5344 - 5330 - 5311						
Recent Weather:			Light rain last 24 hours, Sunny in the 60's						
TRAIL LANDMARKS		 Trailhead leaves from the west side of the Ponkapoag Trail at intersection marker 5344. Trailhead in located .6 miles north of the Green Dot loop intersection marker 5343. Treadway is road width. Bn leaving trailhead. Small downed limbs to be cleared. Bow saw. Treadway narrows to 5 feet at 100 feet with bn as treadway begins ascending. Pine boughs. Bn at 340 feet as treadway narrows to footpath width. Bn at 430 feet as treadway continues to ascend. Small downed limbs to be cleared at .14 miles. Bow saw. Bn from .15 through .21. Pine boughs. Bn at .24 miles. Pine boughs. Bn at .27 miles. Pine boughs. Unnamed Path Crosses at intersection marker 5330 at .3 miles. Bn at .31 miles. Blue diamond blaze to the right of the treadway at .32 miles. Sbd crosses treadway at .34 miles. 3". Carry off w/bn. Treadway opens to road width at .39 miles. No name Post ends with its intersection with the Ponkapoag Trail at intersection marker 5311 at .51 miles. 							
MINOR		1. Significant Bn as noted in assessment to return treadway to road width if desired.							
PROBLEM AREAS									
MAJOR		None noted							
PROBLEM AREAS									
DISTANCES TO MAJOR INTERSECTIONS		Intersection marker 5344 to Unnamed Path Crosses at intersection							
		marker 53303 miles.							
		• Intersection marker 5344 to No Name Post ends at the Ponkapoag Trail at intersection marker 531151 miles.							
Report prepared by:			K	en Jones – 4/12/08	Ass	essment date:	4/10/2008		

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)
culverts(cv)	large blowdowns (lbd)
rolling dips (rd)	rock work (rkw)
bridges (br)	bridge building (bbd),
bog bridges (bb)	culvert replacement (cr)
rock stairs (rs)	trail relocation (tr),
cribbing (cb)	building new trail drainage (ntd)

retaining walls (rw) ditches (dt) brushing needed (bn) excessive erosion (ee) leaning tree (lt)