TRAIL ASSESSMENT FORM

Doc. #	4005	Trail N	lame	Green Dot Loop – Shea Rink to Skyline Trail	Trail Type:	Wide - M	Condition	Good	
Route:			Shea Rink – 4205 - 4202 – Wampatuck Rd.– 4155 – 4135 – 4120 – 4090 – 4095 – 4142 – 4145 – 4151 – 4174 – 4184 - Wampatuck Rd – Skyline Trail.						
Recent Weather:			No rain last 48 hours, Sunny in the 40's						
Recent V TRAII LAND	1		No i		in the 40's oop trail utiliz The Indian Covever there are arkers and the as I feel pertin at the south en on information the trailhead it hares the same as Skyline Tra dth. Additional readway is not abed over Min way identifies (2) right around to the treadway a cv is being do itz Pond. Ditce as cetion with the the An unname on to the St. Muld not be loce an pipeline state the located on 4 miles. Cemen ascends over of	zing many tracemp Path and e many other old FBH manent. It is additionate treadway and blazing and to blazed until ichiello Bridgichiello Brid	ails in the 400 d Crags Foot resections of caps. They will a Rink parking it is blazed willy blazed with sthe Skyline at 473 feet. It signage requestions approximately of South St. It is a cv running so Cement the treadway be incorporated by the straight. Intersection read by the replacement of the treadway it is the treadway be incorporated by the straight. Intersection read by the replacement of the treadway is to the treadway it is the treadway in with rkw we there is the treadway it is the treadway it is the treadway in with rkw we there is the treadway it is the same in the treadway in the treadway it is the same in the treadway in the treadway in with rkw we the treadway it is the same in the treadway in the tr	Path older l be g area at th green th blue Trail uired at es. cimately Moritz and ed to 3 miles. Is the Signage marker ed (4) other ray. ells and y'sPath/wells	
			1	Cv under treadway at .38 and 24" pipe.					
				Cv under treadway at .40 and drainage structure to	right of tread	way.		wells	
			• (Green Dot Blaze noted o	n pipeline sta	ndpipe at .42	miles.		

- Unnamed Path leaves on right at .47 miles with intersection marker 4202 noted in magic marker on 4x4 blaze post. Should be of the standard intersection marker construction. (5)
- Cv under treadway in streambed at .38 miles. Cement construction with rkw wells. Flowing well. Review in spring.
- Unnamed Path leaves on left at .58 miles. This is the Indian Camp Trail from the old FBH maps. Intersection marker 4125 not present and trail is very overgrown. Blue wooden blaze on tree.
- Treadway enters Wampatuck Road and crosses it diagonally to the left at .71 miles. 4x4 blaze post with magic marker noting 4181 at this location.
- Treadway renters the woods at a fire gate and granite marker labeled Chimney Crags at .75 miles. Fire gate is .7 miles south of the reservation entrance on Wampatuck Road.
- Treadway continues at fire road width and continues to parallel the pipeline.
- Sbd across the treadway at .91 miles. 4". Bow saw.
- Cv to the left of the treadway at .92 miles under pipeline. Cement construction with 2 pipes half full of debris. Water not draining and treadway has 2' of water on it. Needs to be dt into woods on right. (6) (see photo gd1)
- Skyline crosses at intersection marker 4155 at .97 miles. Signage on tree denotes Skyline West to Great Blue Hill and Green Dot to St. Moritz Ponds.
- Lbd across treadway at 1.0 miles. 8" dia. Chainsaw. Blocking Fire road. (7) (See photo gd2)
- Cv to the left of the treadway at 1.03 miles under pipeline. Cement construction with 2 pipes half full of debris. Water not draining and treadway has 2' of water on it. Needs to be dt into woods on right.
- Fire road partially blocked by new tree growth at 1.05 miles. Cut back.
- Cv to the left of the treadway at 1.11 miles under pipeline. Cement construction with 2 pipes half full of debris. Water not draining and treadway has 2' of water on it. Needs to be dt into woods on right.
- Bn at 1.12 miles.
- Unnamed path leaves on left at 1.13 miles.
- Cv under treadway at 1.14 miles. Cement work to right of treadway.
- Cv to the left of the treadway at 1.16 miles under pipeline. Cement construction totally impacted. Treadway has 2' of water on it. Needs to be dt into woods on right.
- Pipeline Trail crosses at intersection marker 4135 at 1.17 miles.
- Bn at 1.19 miles. Lopper work.
- Bn needed 1.28 through 1.34 miles.
- Cv under treadway in streambed at 1.37 miles. 24" clay pipe. Debris in rkw well on R and L to be cleaned.
- Unnamed path leaves on right at intersection marker 4120 at 1.38 miles.
 Road width connector to Crags Foot Path. Old FBH maps show this as the Furnace Brook Trail.
- Bn from 1.39 to 1.71 miles. Small trees extending into treadway.
- Very minor erosion ascending hill at 1.5 miles.
- Unnamed path enters on left at 1.64 miles. Road width path to Fox Hill.
- Two inches of standing water in treadway at 1.65 miles

- Unnamed path leaves on left at 1.73 miles. Great Dome Foot Path as noted on old FBH maps.
- Treadway enters an intersection at intersection marker 4090 at 1.75 miles. Signage on tree denotes the Green Dot trail leaving on a footpath to the right (northeast). Indian Camp Path continues straight (northwest) at road width to intersection marker 4083 as noted on old FBH maps. Pleasant Trail leaves on the left at road width to intersection marker 4043 as noted on old FBH maps.
- Green Dot trail leaves intersection 4090 on the right (northeast) at 1.75 miles at footpath width. Old FBH maps show this trail as a continuation of the Great Dome Foot Path northeast. Significant cleanup to be completed for next .15 miles (8)
- Bn at 1.75 miles.
- Bd extends into the treadway at 1.78 miles. Needs to be cutback. Bow saw.
- Bd crosses the treadway at 1.78 miles with bn. Bow saw 4-8".
- Lbd crosses the treadway at 1.79 miles. Three limbs. Bow saw.
- Bn at 1.80 through 1.82.
- Bd crosses the treadway at 1.82 miles. 10" Bow saw or axe.
- Bd crosses the treadway at 1.84 miles with bn. 8" Bow saw.
- Crags Foot Path enters on left at intersection marker 4095 at 1.90 miles.
 At this point the treadway returns to road width with the Green Dot
 Trail and Crags Foot Path sharing the same treadway. Green dot blazes continue to identify the trail.
- Bn from 2.02 through 2.22 miles. Small trees extending into the treadway.
- Downed limb at 2.08 miles with bn. 8'. Bow saw and loppers.
- Short Path leaves on left at 2.11 miles. Old intersection marker 4124H in noted at this location. Old FBH maps note this as well.
- Cv under treadway in streambed at 2.32 miles. R to L. Rkw/earthen construction. 30" pipe. Flowing well with minor cleaning required.
- Unnamed path leaves on right at intersection marker 4142 at 2.36 miles. Road width connector to Indian Camp Path. Old FBH maps show this as the Furnace Brook Trail.
- Runoff in treadway at 2.41 miles. Treadway should be have a rkw dt with appropriate dt into woods installed to resolve. (9)
- Old Furnace Brook Path leaves on left at intersection marker 4155 at 2.45 miles.
- Bn at 2.51 miles
- Unnamed path leaves on the right at intersection marker 4151 at 2.54. Treadway is road width. Old FBH maps show this as Crags Foot Path leaving to the Indian Camp Trail. The Quarry Path begins here and shares the same treadway with the Green Dot Trail.
- Unnamed path leaves on the right at 2.58.
- Bn at 2.62 miles.
- Unnamed path leaves on the right at 2.68.
- Unnamed path leaves on the right at 2.71.
- Two rkw wb cross at 2.73 and 2.74 miles. R to L. Need cleaning, add missing rock and dt on left installed.
- Skyline enters on the right at intersection marker 4174 at 2.79 miles. For the next .9 miles, the Green Dot, Quarry Path and the Skyline use the

	same treadway. (4172 old FBH map)
	• Green Dot/Quarry Path leaves the Skyline at intersection marker 4184 at 2.88 miles. Treadway narrows to a footpath at this point.
	Bn from 2.9 through 2.92 miles.
	• Unnamed path enters on the right at 2.94 miles.
	Wampatuck Road crosses at 2.97 miles at a fire gate and a granite marker labeled Quarry Path.
	• Green Dot/Quarry Path reenters the woods on the east side of Wampatuck Road at 2.98 miles.
	• Rkw Cv under Wampatuck Road enters to the left of the treadway at 3.0 miles. 2 pipes with drainage from cv causing minor erosion.
	• Lbd crosses at 3.03 miles acting as wb in wrong direction. Needs to be cut back. (old).
	 Lbd crosses at 3.1 miles. Needs to be cut back. (old). Bn at 3.12 miles.
	 Green Dot/Quarry Path ends with its intersection with the Skyline Trail at 3.14 miles just south of Wampatuck Road.
MINOR	 Green Dot Trail leaves the Skyline Trail on the left at 473 feet.
PROBLEM	Additional blazing and signage required at this intersection, as the
AREAS	treadway is not blazed until .11 mile (1).
AKEAS	Treadway crosses streambed over Minichiello Bridge at .13 miles.
	Bridge missing approximately a dozen treads. Replace (2)
	• Cv running under the pipeline to the right of the treadway at .22 miles.
	Water from cv is being directed onto the treadway and down into South
	St. Moritz Pond. Ditching should be incorporated to resolve this issue. (3)
	• Green Dot enters an intersection with the Pipeline crossing at .23 miles.
	Green Dot Trail turns right (south) at this intersection. Intersection
	marker 4205 as noted on map could not be located and should be
	replaced (4)
	• Unnamed Path leaves on right at .47 miles with intersection marker 4202 noted in magic marker on 4x4 blaze post. Should be of the
	standard intersection marker construction. (5)
	• Cv to the left of the treadway at .92 miles under pipeline. 2 pipe half full of debris. Water not draining and treadway has 2' of water on it. Needs to be dt into woods on right. (6) (see photo gd2)
	• Lbd across treadway at 1.0 miles. 8" dia. Chainsaw. Blocking Fire road.
	(7) (See photo gd1)
	• Green Dot trail leaves intersection 4090 on the right (northeast) at 1.75
	miles at footpath width. Significant cleanup to be completed for next .15 miles (8)
	• Runoff in treadway at 2.41 miles. Treadway should have a rkw dt with appropriate dt into woods installed to resolve. (9)
MAJOR	None noted
PROBLEM AREAS	
DISTANCES TO	• Shea Rink parking lot to Pipeline at intersection marker 420523
MAJOR	miles. Replaced missing marker (4)
INTERSECTIONS	• Shea Rink parking lot to Unnamed Path leaves on right at intersection
	marker 420247 miles. Magic marker on 4x4 blaze post (5)
	Shea Rink parking lot to Wampatuck Road71 miles.

- Shea Rink parking lot to Skyline at intersection marker 4155 .97 miles.
- Shea Rink parking lot to Pipeline Trail at intersection marker 4135 1.17 miles.
- Shea Rink parking lot to Unnamed path leaves on right at intersection marker 4120 1.38 miles. Furnace Brook Trail on old FBH map
- Shea Rink parking lot to intersection marker 4090 1.75 miles. Green Dot. Indian Camp Path N. and Pleasant Trail noted on old FBH maps.
- Shea Rink parking lot to Crags Foot Path at intersection marker 4095 -1.90 miles.
- Shea Rink parking lot to Short Path 2.11 miles.
- Shea Rink parking lot to unnamed path at intersection marker 4142 2.36 miles. Furnace Brook Trail on old FBH maps.
- Shea Rink parking lot to Old Furnace Brook Path at intersection marker 4155 2.45 miles.
- Shea Rink parking lot to unnamed path at intersection marker 4151 2.54. Crags Foot Path on old FBH map.
- Shea Rink parking lot to Skyline at intersection marker 4174 2.79 miles.
- Shea Rink parking lot to Green Dot/Quarry Path leaves the Skyline at intersection marker 4184 2.88 miles.
- Shea Rink parking lot to Wampatuck Road 2.97 miles.
- Shea Rink parking lot to Green Dot/Quarry Path ends with its intersection with the Skyline Trail 3.14 miles

Report prepared by:

Ken Jones

Assessment date:

3/7/2008

GDP1



GDP2:



Abbreviations:

ditches (dt)

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb) small blowdowns (sbd) culverts(cv) large blowdowns (lbd) rolling dips (rd) rock work (rkw) bridge building (bbd), bridges (br) bog bridges (bb) culvert replacement (cr) rock stairs (rs) trail relocation (tr), building new trail drainage (ntd) cribbing (cb) retaining walls (rw) brushing needed (bn)

excessive erosion (ee)

leaning tree (lt)