## TRAIL ASSESSMENT FORM

	treadway.			
	Crags Foot Path ends with in	1	1	
	intersection marker 4155 at	.79 miles. Signage on tr	ee denotes Green	
	Dot and Skyline East to St.	Moritz and Skyline Wes	st to Great Blue.	
MINOR	1. Runoff in treadway at .51 m	iles. Treadway should h	ave a rkw dt with	
PROBLEM	appropriate dt into woods in	•		
	2. Erosion noted in the treadwa		d along the	
AREAS	treadway to .75 miles. Need			
	resolve.(2)	s at on left of fieldway		
MAJOR	None noted			
PROBLEM				
AREAS				
DISTANCES TO	• Trailhead intersection mark	Trailhead intersection marker 4091 to Green Dot Loop Trail enters at		
MAJOR	intersection marker 4095	intersection marker 409509 miles.		
INTERSECTIONS	• Trailhead intersection mark	Trailhead intersection marker 4091 to Short Path leaves on left21		
INTERSECTIONS	miles.			
	Trailhead intersection marker 4091 to intersection marker 414246			
	miles. Unnamed path (Furn;	miles. Unnamed path (Furnace Brook Trail)		
	Trailhead intersection marker 4091 to Old Furnace Brook Path at			
		intersection marker 414555 miles.		
	Trailhead intersection marker 4091 to Crags Foot Path leaves on the			
		right at intersection marker 415164 miles.		
	-	•		
		Trailhead intersection marker 4091 to intersection marker 415371		
	<b>–</b> 1 1	miles. Crag Trail (FBH) and Crags Foot Path.		
		Trailhead intersection marker 4091 to Skyline Trail78 miles		
		Trainioud intersection marker 1091 to chags 1 oot 1 all chas at		
	intersection marker 415579 miles.			
<b>Report prepared by:</b>	Ken Jones	Assessment date:	3/13/2008	

## Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)
culverts(cv)	large blowdowns (lbd)
rolling dips (rd)	rock work (rkw)
bridges (br)	bridge building (bbd),
bog bridges (bb)	culvert replacement (cr)
rock stairs (rs)	trail relocation (tr),
cribbing (cb)	building new trail drainage (ntd)
retaining walls (rw)	brushing needed (bn)
ditches (dt)	excessive erosion (ee)
	leaning tree (lt)