TRAIL ASSESSMENT FORM

Doc. #	4019	Trail N	ame	Short Path South	Trail Type:	Wide - M	Condition	Good
Route:			Sawcut Notch Path - Crags Foot Path					
Recent Weather:			No rain last 24 hours – Partly cloudy in the 40s					
TRAIL			Trailhead leaves from the south side on Sawcut Notch Path					
LANDMARKS			 approximately .5 miles west of intersection marker 4180. Old FBH map intersection marker 4133 noted at the trailhead. Treadway is road width. Lbd crosses the treadway and Sawcut Notch Path at the trailhead 20' w/bn. Chainsaw removal required. (1) see photo sp1 Trail begins ascending at 315 feet. Trail begins descending at .1 miles and continues to end. Rkw cb to left and right of treadway from .15 through .17 miles. Cv under treadway at .17 miles. Rkw/earthen construction. Cleaning of dt and wells required (1) Short Path ends with its intersection with Crags Foot Path at .21 miles Old FBH map intersection marker 4124H noted at this trailhead. 					
MINOR PROBLEM AREAS		 Cv under treadway at .17 miles. Rkw/earthen construction. Cleaning of dt and wells required (1) Need a water bar just before the little triangular intersection. After a heavy rain there was a small pool to the left of the path and water was flowing down Short Path onto Sawcut. A bar would direct it to the area that we drained with the stone bar 						
MAJOR PROBLEM AREAS DISTANCES TO			 None noted Sawcut Notch Path to Crags Foot Path21 miles 					
MAJO: INTER	R SECT	IONS					2/27/2000	
Report prepared by:			K	en Jones 3/27/2008	Asse	essment date:	3/27/2008	

SP1:



Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb) small blowdowns (sbd) culverts(cv) large blowdowns (lbd) rolling dips (rd) rock work (rkw) bridge building (bbd), bridges (br) culvert replacement (cr) bog bridges (bb) rock stairs (rs) trail relocation (tr), building new trail drainage (ntd) cribbing (cb) brushing needed (bn) retaining walls (rw)

ditches (dt)

brushing needed (bit)

excessive erosion (ee)

leaning tree (lt)