

Friends of the Blue Hills

Trail Volunteer Work Report

Work date (mm/dd/yy): 4/19/09

Report date: 4/20/09

Your name: Bob Walcott

List Volunteers working with you:

Benjamin David Walcott

Trail Name: Wolcott

Section Name/Description:

Five Corners to Trailside Museum north parking lot, Rt. 138

Work Completed (Please be specific with location of work. Note hazards & potential hazards addressed if applicable):

Removed large 6' tree cut section from running water ditch and small section of tree from green dot trail near near parking lot. Cleaned leaves, mud, rocks, etc, from 5-6 culverts and ditches around 1085

Total Hours (# of people x hours worked): 3.00

Work Remaining:

8 hours cleaning many culverts and ditches. Wolcott has a large number of culverts and ditches. I always seem to underestimate the work remaining. Very active day with people and families with dogs enjoying the Wolcott Path.

Other comments (areas of concern, wildlife sightings, trail markings and signage condition, need for re-route, possible encroachment):

Trail slowly eroding across Wolcott at a large culvert near 1085. 1-2' of water soaked leaves 6" below bottom edge of culvert - not draining thru culvert therefor eroding edge of trail next to large culvert.

Forward completed electronic form to: Dexter Robinson @ dexpdoc@gmail.com