

Friends of the Blue Hills

Trail Volunteer Work Report

Work date (mm/dd/yy): 2/17/09

Report date: 2/19/09

Your name: Alexandra Echandi

List Volunteers working with you:

SCA Crew Members (7) + me

Trail Name: Braintree Pass Path, Bouncing Brook Path

Section Name/Description:

Red dot from Route 28 parking lot to intersection marker 3073

Work Completed (Please be specific with location of work. Note hazards & potential hazards addressed if applicable):

Culvert Clearing: Culvert basins dug out and rebuilt on certain locations; Clearing of ditches leading to the culverts; Clearing of vegetation around the culverts.

Approximately 6 culverts were worked on. one culvert between 3042 and 3073 is collapsed and needs to be replaced (old metal culvert). Another culvert in that same section was not cleared due to the large volumes of water on the upstream side (looks like a pond). DCR will return to clear this culvert.

Total Hours (# of people x hours worked): 64

Work Remaining:

Replacement of old metal culvert; Clearing of culvert mentioned above.

Other comments (areas of concern, wildlife sightings, trail markings and signage condition, need for re-route, possible encroachment):

Maintenance work needed on the gas line close to Chickatawbut Road. Culvert on easement totally clogged- We tried unclogging it but might require heavy equipment. Additional drainage issues around this location. District manager contacted to relay the information to the gas company.

Forward completed electronic form to: Dexter Robinson @ dexpcdoc@gmail.com