Friends of the Blue Hills

Trail Volunteer Work Report

Work date (mm/dd/yy): 2/18/09 Report date: 2/19/09

Your name: Alexandra Echandi

List Volunteers working with you:

SCA (8), Joe Sloane (I was not working at this site)

Trail Name: Bouncing Brook Path

Section Name/Description:

Between Kitchamakin foot trail and 3130; Culvert on Wampatuck Path

Work Completed (Please be specific with location of work. Note hazards & potential hazards addressed if applicable):

Culvert Clearing: re established several drainage ditches and cleared approximately 4 culvert basins. Vegetation cleared around the culverts, culverts were rearmored on the inflow site. Outflow was dug out to keep the water in its path-- Culvert on Laurel Path downstream from culvert on Bouncing Brook was cleared and reopened to let the water flow appropriately from one culvert to the next.

Burried CCC Stone culvert on Wompatuck was clear on the outflow side- Inflow opening could not be located- vegetation cleared in the area.

Total Hours (# of people x hours worked): 50

Work Remaining:

fill + water bars required on sections of the red dot

Other comments (areas of concern, wildlife sightings, trail markings and signage condition, need for re-route, possible encroachment): need to locate inflow for CCC stone culvert at Wampatuck Path

Forward completed electronic form to: Dexter Robinson @ dexpcdoc@gmail.com